

**CONFIDENTIAL**

file

605 T-018

25X1

13 April 1960

25X1

AIR MAIL

ORIGINAL CL BY 235779  
☐ DECL ☐ REVW ON 2010  
 EXT BYND 6 YRS BY SAMC  
 REASON 3 d (3)

DOC <u>16</u>	REV DATE <u>30 APR 1980</u>	BY <u>018373</u>
ORIG COMP <u>33</u>	OPI <u>36</u>	TYPE <u>01</u>
ORIG CLASS <u>A</u>	PAGES <u>1</u>	REV CLASS <u>C</u>
JUST <u>22</u>	NEXT REV <u>2010</u>	AUTH: NR 16-2

25X1

Dear Sir:

Under separate cover we are returning for modification and repair two video amplifiers, type VA-9. One of the amplifiers is inoperative due to the absence of Q-101 a 2N346 transistor. This element was removed in order that one of the video amplifiers, type VA-9 modified which had a bad transistor of this type could be restored to operation. The defective transistor is attached to the inoperative video amplifier.

Very truly yours,

25X1

DGB/cg

**CONFIDENTIAL**